

Solving environment-related business problems worldwide

www.deltaenv.com

27141 Aliso Creek Road • Suite 270 Aliso Viejo, California 92656 USA 949.362.3077 800.477.7411 Fax 949.362.0290

April 13, 2006

Mr. Jackson Crutsinger San Bernardino County Fire Dept. Hazardous Materials Division 620 South E Street San Bernardino, California 92415 Sent by FedEx

Subject:

Quarterly Site Status Report Submittal

Dear Mr. Crutsinger:

On behalf of Atlantic Richfield Company, Delta Environmental Consultants, Inc. is submitting the enclosed Quarterly Site Status Report for the First Quarter 2006. The enclosed quarterly report was prepared for the following ARCO Facility:

ARCO Facility No.	SBCFD Case No.	Location
3081	93056	12201 Mountain Avenue, Chino

If you have any questions or comments concerning this correspondence, please contact David White at (714) 228-6782.

Sincerely,

DELTA ENVIRONMENTAL CONSULTANTS, INC.

Amy R. Mora Project Manager

Enclosure:

Atlantic Richfield Company Quarterly Site Status Report

cc:

Mr. David White, Atlantic Richfield Company, La Palma, California Ms. Carole Farr, SECOR International, Inc., San Diego, California



ATLANTIC RICHFIELD COMPANY QUARTERLY SITE STATUS REPORT **FIRST QUARTER 2006 APRIL 15, 2006**

Facility No.:

3081

Address:

12201 Mountain Avenue, Chino, California

Atlantic Richfield Co. Env. Manager / Phone No.:

Mr. David White / (714) 228-6782

Consulting Co. / Contact Person / Phone No.:

SECOR International Incorporated / Ms. Carole Farr /

(619) 296-6195

Primary Agency / Contact Person/Regulatory ID No.:

County of San Bernardino Fire Department (SBCFD

Mr. Jackson Crutsinger / Case No. 93056)

Other Agencies to Receive Copies:

NA

WORK PERFORMED THIS QUARTER (First - 2006):

Submitted the Quarterly Site Status Report to the SBCFD.

2. Received a letter of case closure from the SBCFD dated March 20, 2006.

WORK PROPOSED FOR THE NEXT QUARTER (Second – 2006):

Prepare for the destruction the soil vapor extraction (SVE) wells and decommissioning the SVE system.

Current Phase of Project:

Post-Remediation

Frequency of Sampling:

NA

Frequency of Monitoring:

NA

Permits for Discharge (No.):

SCAQMD #F58869

Approx. Depth to Groundwater:

Measured

Estimated

Groundwater Gradient:

NA NA

(Magnitude)

NA

(Direction)

ATTACHMENTS:

Site Location Map (Figure 1)

Site Map (Figure 2)

DISCUSSION:

Case closure was granted by the SBCFD in a letter to Atlantic Richfield Company dated March 20, 2006. This will be the final Site Status Report submitted for this site.


If you have any questions or comments concerning this correspondence, please contact David White at (714) 228-6782.

DELTA ENVIRONMENTAL CONSULTANTS, INC.

Amy Mora

Project Manager

4/13/06 Date



GENERAL NOTES:
BASE MAP FROM U.S.G.S. 1967
ONTARIO QUADRANGLE
CHINO, CA
7.5 MINUTE TOPOGRAPHIC MAP
PHOTOREVISED 1981






FIGURE 1 SITE LOCATION MAP ARCO FACILITY NO. 3081 12201 MOUNTAIN AVENUE

CHINO, CA
PROJECT NO. DRAWN BY
AM00-807
FILE NO. PREPARED BY
SLM 1 C. OTA
DATE REV. REVIEWED BY
6/24/02



